	lay, 5/14/2007 7:15:31 AM Johnston	Proces	ss Sheet		1011
Customer Job Number Estimate Number P.O. Number Prist Issue Previous Run Written By Checked & Approve	ed By : est rev A 07.00 10 nev	ALL /MED FAB	Part Number Drawing Number Project Number Drawing Revision Material Due Date	: HARNESS ASSEMBLY : D412702115B : ICA D412-702 P.79 : N/A : D : \(\frac{1}{2} \) : 5/15/2007 \text{Qty:}	Um: E
Additional Product					
C #-			Description :		
Seq. #:	Machine Or Operation:		Description :		
					(Pro)
Comme	ent: DOCUMENT CONTROL	NATE OFFICIAL		(4)	Kt -
2.0	type labels per PPP D412-702 D35735	2-115B CHG001 ADAPTER			page
		1			
Comme	ADAPTER B3/863	Total: A.0000 Eac	h(s)		
30	D3579046		R HARNESS RH	(0)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
		1	77		
□ Comme	nt: Qty.: 1.0000 Each(s)/Unit SHOULDER HARNESS RH batch: R 32/15	Total: #.0000 Eac	h(s)		
4.0	152	CLIP			
		1			
		Total: A:0000 Each	n(s)		
+	CLIP batch: 104426				
5.0	MS24693S272	Screw 4			
Commer	nt: Qty.: 4.0000 Each(s)/Unit Screw batch: N 8967 ~	Total: 16,0000 Eac	h(s)	<i>\(\lambda\)</i>	War locke
	Daton. // O / -			/ /	VCO 1105 11 L

w/o split m /05/16 Use contact cement D3569-3 do not Study 0705. 07-05-16 M102/65 07/05/16 SEE W/0 32337

.

enc"

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: HARNESS ASSEMBLY

Part Number: D412702115B

Job Number: 32339 Job Number: Seq. #: 60

Machine Or Operation: AN960JD10LL

Washer 16.0000 Each(s)

Nut

4

Description:

Comment: Qty.: 4.0000 Each(s)/Unit Washer

4.0000 Each(s)/Unit

Total:

Total:

16.0000 Each(s)

Nut 11/0421)batch:

8.0

Comment: Qty.:

Comment: Qty.;

DECAL

4:0000 Each(s)

1.0000 Each(s)/Unit Total:

32086

batch:

SMALL & MEDIUM FAB RESOURCE 1

Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per dwg ICA D412-702 p.79

INSPECT WORK TO CURRENT STEP

Comment: INSPECT TO CURRENT STEP

110 PACKAGING PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-702-1158 CHG001

Location:

PPP Rev:


Inspection level of D

Job Completion




& Brusil

ICA-D412-702 ICA Page 79 (80 blank) of 98



DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-17A AND D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES (BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES NCONTROLLED COPY (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANG	SES				-
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
0705-16	(w/o split for aty I to ship on this wo	ml	0405-16	(Mos-16	6705-16

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	_ Date:	
			QA: N/C Closed:	Date:	

	W	ORK OR	DER NON-CONFORMANC	E (NCR)			
DATE STEP	Description of NC Corrective Action Section B			Varification	Annewal	Annroyal	
	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
3	ches not stick well	UE 07-05, 16		m) 16	07-05-16	U€ 07.05.16	0405-16
			JE JJ				
	STEP 3	STEP Description of NC Section A	STEP Description of NC Section A Initial Chief Eng	STEP Description of NC Section A Corrective Action Section B Initial Action Description Chief Eng Chief Eng	STEP Section A Initial Action Description Sign & Date Initial Chief Eng Banclusing contact Over 100 + 5 + 12 4 well 07-05. 16 werend. M 102565 March 16	STEP Description of NC Section A Corrective Action Section B Verification Section A Chief Eng Chief Eng Chief Eng Chief Eng Chief Eng Corrective Action Section B Verification Section C Section C	STEP Description of NC Section A Initial Chief Eng Ch

NOTE: Date & initial all entries